




Catalogue and Technical update

Industry Leading Range

Product & Service Solutions


“DELPHI ASSISTANCE”



LP1699 and LP1846
both contain 2 Pairs of
pads with a notched
end.

The notched end
**MUST BE
PLACED**
to the top of the
caliper

Incorrectly aligned
pads will result in
the caliper not
closing.
In this case the
Pads or Caliper
should
**NOT BE
FORCED OR
STRUCK**
as this will
damage the Pads



DELPHI MEETING ALL YOUR CUSTOMER NEEDS